

Calga Sand Community Consultative Committee – Annual Report for 2018-2019

CCC / Project Name:	Calga Sand	Reporting Period:	May 2018 to May 2019
Independent Chairperson:	Lisa Andrews	Proponent Contact:	Andrew Driver

1. Executive Summary

The Calga Sand Quarry is located off Peats Ridge Road, 1.7 km north-northwest of the Calga Interchange on the M1 Freeway. The quarry has operated periodically since the late 1960's and more formally since the early 1990's.

The site is located adjacent to the Australia Walkabout Wildlife Park.

The project operates in accordance with its approval and a Community Consultative Committee has been meeting regularly since 2011 and operates in accordance with the guidelines. The membership consists of:

- Six local community representatives
- Three company representatives (Hanson); and
- One Independent Chairperson.

The meetings are held bi-annually in May and November. However, an extra-ordinary meeting was held in February 2019 following requests from members for a detailed presentation on ground water, surface water and bore monitoring.

The committee receives information from the project operators regarding its compliance with the conditions of consent including the monitoring of environmental, air, noise and water management on the quarry site.

A Community Open Day was arranged in May 2019 with members being invited to attend.

The CCC is an effective communication forum between the community and the company, who have worked hard to establish an improved working relationship with the committee following the purchase from the previous owner. It now functions well and accordingly, fulfils its objectives under the Department's guidelines.

2. CCC activities over last 12 months

- The committee met in May, 2018 November 2018, May 2019 with an extraordinary meeting in February 2019.
- Attendance is consistent with some apologies registered depending on competing obligations with volunteer members.

3. Key issues

Trending topics of committee discussion can be summarised as:

Issue	Actions Taken	Outcome
Concerns with truck movements to and from the site	Drivers operate under a Drivers Code of Conduct and the company demands strict compliance. Any complaints are addressed immediately. It is noted however, that not all issues are attributable to Hanson trucks & its contractors, as a number of trucks use this area.	Hanson are currently working with RMS to reduce the sign posted speed limits in the area and improved turning lanes into and out of the site.
Illegal Motorbike riders	Motorbike riders are entering the site illegally, which has required Hanson to install concrete barriers, fencing & padlocks. Unfortunately, these barriers are often vandalised.	Hanson encourage neighbours to contact them when activities are observed/heard, which allows staff to attend the site immediately.
Weed eradication	Monthly weed control works are undertaken by a contractor.	Ongoing maintenance carried out.
Groundwater Monitoring	Detailed presentation from Hydrogeologist & Independent Groundwater Consultant in February 2019 to discuss bore monitoring and groundwater data results.	Ongoing details provided at each CCC.
Bushfire Management	The RFS will be undertaking hazard reduction works.	CCC members to be notified when works are to be carried out.


4. Focus for next 12 months

The planned activities for 2019 will be guided by the contributions of the CCC members. These activities are likely to include:

- A site inspection.
- Updates on environmental monitoring of the site, including weed maintenance program, groundwater/surface water and bore monitoring.
- Continued rehabilitation of the site with results presented to the CCC.
- Drivers' continued compliance with the road rules and driving to conditions in accordance with the Drivers Code of Conduct.

To the best of my knowledge, there are no outstanding or emerging issues that have not been addressed.

CCC minutes are available on the project website.

Signature of Chair:	
Date:	27 May 2019